

16BC067A-A

Assembly Instruction

Part Ist: Hardware List: Image: Im	217998 Assembly Instruction								
A Seat Image: Constraint of the seat of t	Parts List: Hardware List:								
A Seat I IUS (M6,I D 65,0D 12) 4 B Base I I IUS (M6,I D 65,0D 12) 4 D01 Allen Wrench (M6) I I I I I I I I I I I B Base I	REF	PART NAME	PART IMAGE	Q'TY	REF.	PART NAME	PART IMAGE	Q'TY	
Diagram:	A	Seat		1	105			4	
(M6) 004 Washer (M6,I D 6.5, OD 12) Diagram: 01 01 01 01 01 01 01 01 01 01	в	Base	A	1	020	Bolt (M6×25MM)		4	
Diagram:				·1	001			1	
A Complex Stars									
Assembly Step: Step1:Pls remove protective wrapping and lay all parts on the floor.Make sure all parts packed in carton									

against attached parts list are presented. Step2:Place a protective soft material before laying the seat on floor, assemble the base as the above diagram.

Step3:After all parts are aligned and tightened properly,pls turn over the bar stool carefully with a second person's assistance.Make sure the legs are on a flat surface.