

ASSEMBLY INSTRUCTIONS

ITEM NO: B8270 / B8280 - 1 & - 11 DRESSER & MIRROR

BOX OF DRESSER

ITEM	DRAWING	DESCRIPTION	QTY
A		DRESSER	1


BOX OF MIRROR

ITEM	DRAWING	DESCRIPTION	QTY
В		MIRROR	1
С		MIRROR SUPPORT	2

(BOX OF MIRROR) HARDWARE LIST

ITEM	DRAWING	DESCRIPTION	QTY
1	& minus	FLAT HEAD SCREW (M4 x 32mm)	8
2		Assembly Tool Not Included	1





THE HARDWARE IS LOCATED IN THE PACKING ITEMS

NOTE: MUST TIGHTEN SCREWS PERIODICALLY. WITH USE SCREW MAY BECOME LOOSE. CHECK TIGHNESS OF ALL SCREW EVERY 6-8 WEEKS.

CLEANING INSTRUCTION